LAND APPLICATION OF BIOSOLIDS SITE INSPECTION FORM

GENERAL INFORMATION: Date: 19 May 2004			
County: Charlotte Contractor/Municipality: Nutri-Blend, Inc.			
Name (Owner/Operator): various			
Inspected by: Charlie Swanson			
Others present: alone			
FIELD DATA/OBSERVATIONS:	ATIONS: Time: from 10:00 am til 2:00 p.m.		
Weather: Sunny, 80s, med-low humidity	Soil conditions: ok		
Biosolids source: Middlesex N.J.	Biosolids type: lime stabil	ized	
Application rate WT/ac: ~70% PAN			
Crop and expected yield: corn			
BIOSOLIDS APPLIED: () Liquid	(XX) Dewatered		
MODE OF APPLICATION: (XX) Surface () Surface w/incorporation () Injection			
APPLICATION LIMITED BY: (XX) Nitrogen () pH () Metals			
() Max. hydraulic loading (liquid biosolids)			
() Max. solids loading (15 dry tons/acre)			
() Other (specify):			
FIELD OBSERVATIONS		YES	NO
Buffers observed:		XX	
Uniform application:		XX	
Proper field records:		XX	
Signs of runoff:			XX
Trucks non-spill/watertight:		XX	
Condition of haul route satisfactory:		XX	
ODORS PRESENT: (XX) None () Normal () Above normal*			
If yes, type () Lime () Ammonia () Sulfides () Septic () Other			her
OVERALL CONDITION OF SITE: (XX) Good () Fair () Poor			

LAND APPLICATION OF BIOSOLIDS SITE INSPECTION FORM (Cont.)

Jack Wilson Site March 26, 2003

COMMENTS: (*explain):

Dr. Cal Sawyer had received an email message on Monday, 17 May 2004 from a Charlotte County Board of Supervisor member. A complaint was registered with VDH that Nutri Blend's land application operations may be causing a vector attraction problem by excessive flys on nearby farms. A list of four nearby farm families located on Germantown and Bethlehem Roads were submitted in the fax to VDH.

Mr. Swanson went by the County Administrator's office and spoke with Susan Adams about the locations of the complainants and other related biosolids issues. Mr. Swanson next was able to locate one of the addresses and visited the nearby field that had been spread with biosolids and currently had corn growing on this field (about a foot tall in height). Mr. Swanson visited with the resident and inquired about the flys and attempted to determine the time frame for appearance of the flys. The resident stated that flys were present in the spring (2004) and also in the previous year's spring (2003). The pictures that were emailed were apparently taken during the Spring 2003. No large flys similar to those seen in the pictures were present. A few normal house flys were seen on the resident's carport, which had a white color. However, the resident owned the surrounding farm containing a herd of beef cows.

Mr. Swanson was unable to locate one of the listed residences. Mr. Swanson did locate another resident, who stated that the flys were present in the spring for about three weeks and they were thick on the outside of that residence. The resident spoke of a dislike of the practice of land application of biosolids. At this time there were no large flys present at the residence.

Mr. Swanson visited another of the listed residents, who also farmed and raised beef cattle and they also stated that they had large flys present near their home in the spring.

COPIES: VDH/Central - Division of Wastewater Engineering

Nutri-Blend, Inc. - Dave Smith

Charlotte County

Charlotte County Health Department